



Report #: SL08A-000002

Syracuse 6085 Court Street Road Suite A Syracuse, NY 13206 Phone: 315.699.5281

Fax: 315.699.3374

Client: Project:

O'Tooles Stone & Gravel 70 Oak Hill Road Moravia, NY 13118

ST4872 O'Tooles Stone & Gravel Laboratory Testing LSA 2024 Syracuse, NY 13206

Sampling Information

Sample Number:	114688	Sampled By:	Client
Sampling Method:	Not Provided	Sample Date:	06/24/2024
Sample From:	Not Given	Material Type:	Granular Material
Color/Material Description: Brown bank run gravel			

Test Results

Test Completed By: Wilburn, Jon **Test Completed Date:** 07/10/2024 Sieve Analysis Data Sieve Size Percent Spec. Spec. **Passing** Result Range 100 100 mm (4 inch) 100 ---75 mm (3 inch) 94 ---90 ---63 mm (2.5 inch) 92 ---80 50 mm (2 inch) 88 70 37.5 mm (1.5 inch) 83 ------25 mm (1 inch) 71 Passing 19 mm (3/4 inch) 62 ---50 12.5 mm (1/2 inch) 52 40 6.3 mm (1/4 inch) 41 ---4.75 mm (No. 4) 37 ------30 2 mm (No. 10) 27 ---20 850 µm (No. 20) 18 ------10 425 µm (No. 40) 11 250 µm (No. 60) 8 180 µm (No. 80) 6 0 00 150 µm (No. 100) 5 Sieve Size (mm) 75 µm (No. 200) 4.4 Test Specification: ASTM C136/C117

Jon Wilburn Lab Supervisor 07/11/2024